Parts Change Information

SUBJECT → Connection of Job Separator With FR Series

APPLIES TO: **Job Separator III** PARTS COMPATIBILITY: **Conditionally Compatible**
NEW PART #: **018-33153-001** NEW DESCRIPTION: **Job Separator Bracket;GF**
DOCUMENT NO: **20390**

Summary: Previously, the Job Separator was shipped with two brackets: one to connect with the RA and one to connect with the GR. These brackets are no longer included. The Job Separator is now shipped with a single bracket which will connect to either FR or GR machines.

New Part Number	New Part Name
018-33153-001	Job Separator Bracket; GF

Note: Boxes containing the new-style bracket can be identified by a red, circular label affixed to the front and side next to the product code (see diagram).



Procedure: Job Separator Bracket; GF must be obtained if connection to the FR is required. Order parts as necessary. Parts availablity begins 120 days from issue of bulletin.



018-33153-001
Job Separator Bracket; GF

ISSUE DATE: **9/28/99** SUPERSEDES: DATED: PAGE: **1 of 1**

Copyright:1999 RISO, Inc. All products are trademarks of their respective companies. Specifications subject to change without notice.